03500.017894.

**PATENT** 

# IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: Daniel St. Cyr TOSHIKI NAKAYAMA Art Unit: 2876 Appln. No.: 10/772,359 Filed: February 6, 2004 For: **COLOR IMAGE FORMING** APPARATUS AND COLOR MEASUREMENT CONTROLLING **METHOD THEREFOR** U.S. Patent No.: 7,111,784 B2

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Issued: September 26, 2006

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

of Corection

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/18/2007 SZEWDIE1 00000065 7111784

01 FC:1811

January 16, 2007

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Leonard P. Diana
Attorney for Patentee
Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY\_Main 612421v1

# Staple Here Only!

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,111,784 B2

DATED

September 26, 2006

INVENTOR(S) :

TOSHIKI NAKAYAMA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# ON THE TITLE PAGE [74]:

Insert -- (74) Attorney, Agent, or Firm — Fitzpatrick, Cella, Harper & Scinto--.

# COLUMN 3:

Line 26, "driven" should read --driven by--; and Line 60, "affixing" should read --a fixing--.

# COLUMN 12:

Line 3, "reflectance" should read --reflectance.--.

# COLUMN 18:

Line 15, "form" should read --from--; and Line 60, "reading-but" should read --reading-out--.

### COLUMN 19:

Line 13, "form" should read --from--; and Line 62, "image" should read --images--.

# COLUMN 20:

Line 6, "image," should read --images,--;

Line 29, "difference" should read --different--:

Line 53, "fixation" should read --fixation of--;

Line 55, "executes" should be deleted;

Line 65, "a" (second occurrence) should be deleted; and

Line 66, "image" should read --images--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,111,784 B2</u>

No. of add'l. copies @ 30¢ per page

<u></u> \_

TIAN 2 3 2007

Form PTO 1050 (Rev. 3-82) NY\_Main 612421v1

# Stable Here Only!

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,111,784 B2

DATED

September 26, 2006

INVENTOR(S) :

TOSHIKI NAKAYAMA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 21:

Line 4, "step" should read --step,--; Line 24, "of" should be deleted; and Line 25, "image," should read --images,--.

# COLUMN 22:

Line 27, "detecting" should be deleted.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY\_Main 612421v1 PATENT NO. <u>US 7,111,784 B2</u>

No. of add'l. ∞pies @ 30¢ per page



# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,111,784 B2

DATED

September 26, 2006

INVENTOR(S) :

TOSHIKI NAKAYAMA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# ON THE TITLE PAGE [74]:

Insert -- (74) Attorney, Agent, or Firm — Fitzpatrick, Cella, Harper & Scinto--.

# COLUMN 3:

Line 26, "driven" should read --driven by--; and Line 60, "affixing" should read --a fixing--.

## COLUMN 12:

Line 3, "reflectance" should read --reflectance.--.

### COLUMN 18:

Line 15, "form" should read --from--; and Line 60, "reading-but" should read --reading-out--.

### COLUMN 19:

Line 13, "form" should read --from--; and Line 62, "image" should read --images--.

### COLUMN 20:

Line 6, "image," should read --images,--;

Line 29, "difference" should read --different--;

Line 53, "fixation" should read --fixation of--;

Line 55, "executes" should be deleted:

Line 65, "a" (second occurrence) should be deleted; and

Line 66, "image" should read --images--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,111,784 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY Main 612421v1

MAN 2 3 2007

# Stable Here STRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,111,784 B2

DATED

September 26, 2006

INVENTOR(S) :

TOSHIKI NAKAYAMA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 21:

Line 4, "step" should read --step,--; Line 24, "of" should be deleted; and Line 25, "image," should read --images,--.

# COLUMN 22:

Line 27, "detecting" should be deleted.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,111,784 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY\_Main 612421v1

FJAN 2 3 2001